

ТАБЛИЦА 9. Размеры и масса фильтров-осушителей со сменной вставкой

Номер по каталогу	Диаметр соединений			Размеры [мм]						Масса [г]	
	под пайку ODS		под сварку W	D_1	D_2	H_1	H_2	H_3	P		
	[дюйм]	[мм]	[мм]								
4411/5A	5/8	16	—	121	149	148	235	185	90	5360	
4411/7A	7/8	22				154	241		96	5405	
4411/9A	1 1/8	—								5395	
4411/11A	1 3/8	35				159	246		101	5464	
4411/13A	1 5/8	—				171	258		113	5435	
4411/M42A	—	42								5410	
4411/17A	2 1/8	54				162	249		103	5585	
4412/7A	7/8	22				296	383	324	96	6880	
4412/9A	1 1/8	—							101	7015	
4412/11A	1 3/8	35				312	399			113	6985
4412/M42A	—	42				303	390			103	7136
4412/17A	2 1/8	54				442	529			101	8510
4413/11A	1 3/8	35				454	541			113	8470
4413/13A	1 5/8	—									8445
4413/M42A	—	42				595	682				9940
4414/13A	1 5/8	—				586	673		103		10 010
4414/M42A	—	42									
4414/17A	2 1/8	54									
4423/17A	2 1/8	54	60,3	163	200	518	641	600	142	18 000	
4423/21A	2 5/8	—	76,1						18 200		
4423/25A	—	—	88,9						162	18 400	
4424/25A	—	—	88,9			21 600					
4424/33A	—	—	114,3			760	172	22 000			

